CONSTANT CLIMATE CHAMBER

Sr. #	Specification/Description of Items	Qty Required
	Constant Climate Chamber	01
	1. Purpose:	Complete
	For storage of X-ray films & radiographs under controlled conditions of	Unit
	temperature & humidity.	
	2. <u>Technical Data/Specifications:</u>	
	2.1 Temperature Range: 0 – 30 °C	
	2.2 Temperature Deviation from Set Value: ± 2.0 °C	
	2.3 Humidity Range: 20 – 60 % RH	
	2.4 Humidity Deviation from Set Value: ± 3.0 % RH	
	2.5 Internal Dimensions (Aprox): (H x W x D) (5.0 x 3.5 x 2.2 ft)	
	2.6 Inner Chamber: Made of Stainless Steel	
	2.7 Unit Doors: 02	
	2.8 Number of Shelves: 4 - 6 (Made of Stainless Steel)	
	2.9 Lockable Door Handle	
	2.10 Internal Lighting (LEDs)	
	2.11 Non-Frost	
	2.12 Sound level (Noise): minimum	
	2.13 Make: Imported	
	3. Control Features:	
01	3.1 Calibration option for temperature and humidity devices/sensors	
	3.2 Digital display of temperature & humidity	
	3.3 Automatic water and wastewater management	
	4. Operating Conditions:	
	4.1 Temperature Range: 10 to 40°C	
	4.2 Humidity Range: 10 to 90 %	
	4.3 Electrical Supply: 400/220 VAC ± 10%, 50 Hz	
	5. Limit of Supply (Standard Accessories):	
	Chamber must be supplied with standard accessories.	# 4 AL PEO
	6. Optional Accessories:	
	All types of available optional accessories may be quoted by supplier.	
	7. <u>Spares:</u>	
	Essential spares for 05 years operation minimum including:	
	7.1 Temperature sensor & controller	01 Set
	7.2 Humidity sensor & controller	01 Set
- 1	7.3 Protection relays, LED bulbs, switches, fuses.	01 Set
	7.4 Any other spares which are essential for maintenance may be quoted	500
	8. Documentation/Manuals:	
	All documents including accuracy certificates, operating manuals, troubleshooting	
	& maintenance manuals, electrical & control circuit diagrams will be provided in	
	English.	